


GENERALSCAN

GS V21

Digital Tape Measure

QUICK START GUIDE



EN

■ GENERALSCAN QUICK START GUIDE

This guide introduces the basic using method and the basic parameters of digital tape Bluetooth measure GS V21, you can adjust the settings of your device according to your wishes and get it work easily. If any further questions, please contact us via email **support@generalscan.cloud**.

■ COPYRIGHT

GENERALSCAN reserves the right to make changes to any product to improve reliability, function, or design.


GENERALSCAN does not assume any product liability arising out of, or in connection with the application or use of any product, circuit, or application described herein.

■ UNPACKING

1




2




① GS V21 x 1 ② Type-C Cable

■ FEATURES



■ POWER ON AND POWER OFF

Power on

Press  for about 3 seconds to turn it on.

Power off

Press  button for about 3 seconds to turn it off.


■ HOW TO MEASURE

Pull out the steel tape to start measure directly.

Short press  to record the measurement.

The effective measurement distance is from the ruler hook to the measurement benchmark.

■ SWITCH MEASURE MODE

Short press  to switch length measurement, area measurement, and volume measure.



Length Measure



Area Measure




Volume Measure

■ SWITCH BENCHMARK


Short press  to switch front benchmark and rear benchmark.

The benchmark icon will stay on the left above corner.

 shows in display when it is in front benchmark state.

 shows in display when it is in the state of rear benchmark.

■ SWITCH UNIT





Long press  to switch mm, cm, m, Inchx0.1, FTx0.01, and Inchx1/16&FT. The unit icon will be shown on the display at the right bottom corner.

■ ZERO OUT





Short press  to forcibly clear the current measurements.

■ MENU OPERATION



Menu Function

| Button | Function | |
|--|--------------------------------------|---------------------|
| | Short Press | Long Press |
|  | Exit Menu | |
|  | Page Up | Enter the Menu Page |
|  | Page Down | |
|  | Enter the Selection Page/ Turn on | |

■ INQUIRY MEASURE HISTORY

 In this page, short press  to enter into history inquiry page, short press  or  to page up or page down.





■ INQUIRY DEVICE INFORMATION

 In this page, short press  to check the detailed information about the device.

■ OPEN OR CLOSE VOICE

 In this page, short press  to enter into selection page, short press  or  to open or close voice.

■ SCREEN ROTATION

 In this page, short press  to enter into the selection page, short press  or  to confirm the orientation of screen.

■ SOFTWARE DOWNLOAD

Please download the software from our website **www.generals-can.cloud** to record and transfer the measurement data.

Service Information

If you have a question of your GENERALSCAN barcode scanner, please visit our service page for assistance.

www.generalscan.cloud/services

QUICK USER GUIDE

Email: Support@generalscan.cloud

©2023 GENERALSCAN All rights reserved

Version 1.1



886783025001